






INSTALLATION INSTRUCTIONS

Shielded Aerial Service Wire Connector – EM 3928




electric motion company, inc.

winchester business park • 110 groppo drive • p.o. box 626 • winsted, connecticut 06098 • 860/379-8515 • fax 860/379-7835




4 Add the top plate. Position onto the drop, and tighten with 216 tool.




6 Tighten nut.

7 Cut off excess drain wire and core wrapper. Terminate conductors.



5 Wrap drain wire around stud and add second nut.



8 Terminate connector at the ground post in NID.